

FIG. 1





FIG. 2



10/533181

FIG. 3




FIG. 4




FIG. 5




FIG. 6






FIG. 7A



BEFORE CHANGE OF
BEAM SCANNING DIRECTION

FIG. 7B



AFTER CHANGE OF
BEAM SCANNING DIRECTION

FIG. 8A




FIG. 8B




FIG. 9





FIG. 10A**FIG. 10B**